

**SPECIFICATIONS**

**2002 CATERPILLAR D8RII**  
**TRACK TYPE TRACTORS**

**Customer Owned Certified**

Serial #: 6YZ00750  
 Engine Serial #: N/A  
 Transmission Serial #: N/A  
 SMU/Hrs: 1  
 Last Scheduled Oil Sample: N/A  
 Last Cat Track System Inspection: N/A  
 Last Preventative Maintenance: N/A  
 Recommendation: no recommendation

**Features**

- EROPS
- BLADE, SEMI U
- LANDFILL ARRANGEMENT
- AIR CONDITIONER
- RIPPER, MULTI SH
- ENGINE ENCLOSURES
- BLADE, SINGLE ANGLE TILT
- DIFF STEER
- LIGHTING

**Condition**

**.GENERAL APPEARANCE.**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Radiator Grill &amp; Shroud</b>	Fair - GRILL BOLTS MISSING/LATCH BROKEN/HINGE MISSING				
<b>Eng. Enclose Hood / Stack</b>	Fair - BOLTS MISSING/RS. ACCESS DOOR LATCH BROKEN, OTHER SIDE NOT OPERATIONAL				
<b>Fenders</b>	Good				
<b>Fuel Tank</b>	Poor - TANK CAP MISSING, RAG INSIDE				
<b>Crankcase Guard / Battery Box</b>	Good				
<b>Main Frame Welds</b>	Good				

<b>Pre-Cleaner Bowl</b>	Fair - SCREEN BENT				
<b>Cab or Canopy</b>	Fair - ANTENNA BROKEN/RS. DOOR ADJUST/RS. DOOR STRIPPING TORN/				
<b>Steps / Ladder</b>	Good				
<b>Grab Irons</b>	Good				
<b>Paint</b>	Fair				
<b>Hood</b>	Good				
<b>Engine Doors</b>	Fair - LATCHES NOT OPERATIONAL BROKEN				
<b>Sheet Metal</b>	Fair - RR. FUEL TANK COVER DAMAGE/SOME RUST/				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Cleaning Required</b>	Yes				
<b>Notes</b>	HARDNOSE PINS/BUSHINGS WORN				

**.SAFETY ITEMS.**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Safety Decals In Place</b>	Yes				
<b>ROPS</b>	Yes				
<b>Safety Decals Legible</b>	Yes				

**.GAUGES, OPERATOR STATION, CONSOLE.**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Dash Console</b>	Fair - 2 BOLTS MISSING				
<b>Seat Cushion / Arm Rest</b>	Poor - CUSHIONS TORN/ARM REST TORN				
<b>Door Latches</b>	Fair				
<b>Glass/Mirrors</b>	Poor - REAR WINDOW BROKEN				

<b>Seat Belt</b>	Poor - BUCKLE BROKEN				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>ROPS Certification Plate</b>	Yes				

### .ENGINE.

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Oil Leaks</b>	Yes - OIL LEAKS				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Anti-Freeze Color</b>	LOW				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Engine Supports</b>	Good				
<b>Exhaust / Muffler</b>	Poor - EXHAUST LEAKS				
<b>Operating Condition</b>	Poor - NOT OPERATIONAL				
<b>Belts / Pulleys</b>	Fair				
<b>Notes</b>	ENGINE IS NOT OPERATIONAL, FUEL IN OIL PAN				

### .COOLING SYSTEM.

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Hoses</b>	Fair				
<b>Fan</b>	Fair				
<b>Fan Drive</b>	Fair				

### .ELECTRICAL, STARTING AND CHARGING SYSTEM.

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Wiring</b>	Poor - SPLICED				

<b>Lighting</b>	Fair - RF/REARS FLOOD NOT OPERATIONAL				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Ether Aid</b>	Yes - BOTTLE MISSING				

**.TRANSMISSION.**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Seals</b>	Fair - LEAKS UNDER MACHINE				
<b>Lines / Fittings</b>	Fair - LEAKS UNDER MACHINE				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Leaks</b>	Yes				
<b>Notes</b>	ENGINE NOT OPERATIONAL				

**.HYDRAULICS.**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Tank</b>	Good				
<b>Lift Cylinders</b>	Fair - RS. LEAKS				
<b>Tilt Cylinder</b>	Fair				
<b>Hose Lines</b>	Fair - OIL LEAKS UNDER MACHINE				
<b>Pumps &amp; Valves</b>	Fair - LEAKS/RIPPER VALVE LEAKS/OIL LEAKS UNDER MACHINE				
<b>Control Linkage</b>	Fair - LEVER LOOSE				
<b>Ripper Lift Cylinder</b>	Fair				
<b>Ripper Tilt Cylinder</b>	Fair				
<b>Notes</b>	DIAGONAL LINK COVER BOLT MISSING				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
<b>Leaks</b>	Yes				

**.BLADE.**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Face / Moldboard	Fair				
Push Arm	Fair				
Tilt Arms	Fair				
Cutting Edge & Bits	Fair - WORN				
Spill Rack	Fair - DAMAGE				

**.RIPPER / GRAPPLE / WINCH.**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Control Linkage	Good				
Brackets / Studs	Good				
Shanks / GET	Poor - WORN				
Notes	RIPPER PIN LOCK PLATE WELDED ON				

**.UNDERCARRIAGE.**

	Condition - Remarks	Parts	Labor	Approved?	Photos		
Track Frame - Left	Fair						
Track Frame - Right	Fair - RECOIL LEAKS						
	Condition - Remarks	Parts	Labor	Approved?	Photos		
Pins & Bushings Turned?	No						
	Measurement (L)	Measurement (R)	% Worn (L)	% Worn (R)	Total Potential Hours (L)	Total Potential Hours (R)	Photos

Links			77	77				
Pins & Bushings (External)			122	124				
Track Shoes (Width)	24"		27	27				
Idlers Front			90	96				
Idlers Rear			88	102				
Segments			44	40				
Track Roller 1			110	108				
Track Roller 2			85	90				
Track Roller 3			87	83				
Track Roller 4			89	87				
Track Roller 5			85	86				
Track Roller 6			84	84				
Track Roller 7			90	93				
Track Roller 8			109	10				
	<b>Condition - Remarks</b>				<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Link Part Number	8E4506							

**.FINAL DRIVES.**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Planetaries / Differential, Ri	Fair				
Housings, Left	Fair				
Planetaries / Differential, Le	Fair				
Housings, Right	Fair				
Notes	DRIVE AXLES REMOVED THEY ARE INSIDE CAB FLOOR/ENGINE NOT OPERATIONAL				

**.COMMENTS, MISC. REPAIRS, GENERAL REMARKS.**

	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
ENGINE IS NOT OPERATIONAL, FUEL IN OIL PAN				
DRIVE AXLES REMOVED, ARE IN CAB FLOOR				
NOT IN OPERATION FOR SOME TIME/HOUR METER REPLACED				
FUEL TANK CAP MISSING, RAG IN TUBE				